

Photo Summary of Etak Artifacts



Following Software Center Visit by
Stan Honey, Ken Milnes, and Walt Zavoli
April 16, 2018



Left to right: Stan Honey, Ken Milnes, and Walt Zavoli



Taking a screwdriver to an official CHM artifact is discouraged, but under the circumstances ...



Computation Unit



Graphic Display Unit



Map Cassette Tape Unit



**Magnetic Tape
Installed Inside Rear Wheel Rims**



Rear Wheel Rotation Sensors



Vector Compass



Heater Motor Magnetic Sensor



Gyroscope considered but not used in final ETAK design.